

Questions and Answers for RFQ # SIZ25015Q0272 / Exterior Door Upgrade Project

1. Question: S-033 2nd floor front door: Which direction will the door swing?

Answer: The front door is to swing outward

2. Question: S-033 and S-060 2nd floor doors. How many doors total?

Answer: Three (3) Exterior steel grade doors. Two steel doors at S-033 and one steel door at S-060

3. Question: How many door (KABA L1000) locks are there in total?

Answer: Three (3) KABA 1000 door locks.

4. Question: How many window grilles require fire/safety egress escapes?

Answer: Three (3) window grilles require fire/safety egress escapes.